

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, March 10, 2021	Project Contact:	Brian Clauto
Spread I: Pittsylvania	ST15481+47-ST15447+13	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Grading
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-CC16
- ECD's were in place and functioning at the designated crossing.
- Adjacent active construction site has installed silt fence rock outlet breaks that discharge onto the ROW/ clean water diversions.

Routine Maintenance: (72-Hour Deadline from Notification)

- N/a


Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Wednesday, March 10, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, March 10, 2021


- Figure 1: Near St15465+00 SF rock outlet of adjacent property above CWD St15460+00.




- Figure 2: Near St15460+00 SF rock outlet of adjacent property above CWD St15460+00.



- Figure 3: Near St15459+00 SF rock outlet of adjacent property above CWD St15457+00



- Figure 4: Near St15454+00+00 SF rock outlet of adjacent property above CWD St15453+00



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, March 10, 2021

- Figure 5: St15494+77 SF rock outlet installed, ROW discharges water onto adjacent property.



- Figure 6: Near St15457+00 CWD



- Figure 7: CWD pipe outlet near St15453+00



- Figure 8: Designated crossing S-CC16, ECD's are in place.

